

A method of restoration of worn-out ploughshares of tillage machines, in which welding a tire is carried out by arc welding followed by surfacing with sormite powder and strengthening the ploughshare surface by vibration deformation.